

**Chapter 4
List of Figures**

Figure 4.1-1	Core Configuration with Location of Instrumentation.....	4.1-7
Figure 4.2-1	GE12 Fuel Bundle Design.....	4.2-7
Figure 4.2-2	Control Rod Assembly	4.2-8
Figure 4.3-1	Equilibrium Core Loading Map.....	4.3-7
Figure 4.4-1	Power-Flow Operating Map Used for System Response Study	4.4-21
Figure 4.4-2	Power-Flow Operating Map Used for System Response Study (9 RIPs Operation)	4.4-22
Figure 4.4-3	Lungmen NPS Stability.....	4.4-23
Figure 4.4-4	Stability Controls and Protection Logic	4.4-24
Figure 4.6-1	Fine Motion Control Rod Drive Schematic	4.6-28
Figure 4.6-2	Fine Motion Control Rod Drive Unit (Cutaway).....	4.6-29
Figure 4.6-3	Continuous Full-in Indicating Device.....	4.6-30
Figure 4.6-4	Control Rod Separation Detection	4.6-31
Figure 4.6-5	Control Rod to Control Rod Drive Coupling.....	4.6-32
Figure 4.6-6	FMCRD Electro-mechanical Brake	4.6-33
Figure 4.6-7	Internal Blowout Support Schematic	4.6-34
Figure 4.6-8	Control Rod Drive System P&ID (Sheets 1-23)	4.6-35
Figure 4.6-9	Control Rod Drive System Process Flow Diagram.....	4.6-36
Figure 4.6-10	FMCRD Anti-Rotation Devices.....	4.6-37
Figure 4.6-11	Hydraulic Control Unit Flow Schematic.....	4.6-38
Figure 4A-1a	Summary of Haling Condition — 85% Core Flow	4A-3
Figure 4A-1b	Relative Axial Power at 10.2 GWd/MT Cycle Exposure (Haling at 85% Core Flow)	4A-4
Figure 4A-1c	Relative Axial Exposure at 10.2 GWd/MT Cycle Exposure (Haling at 85% Core Flow)	4A-4
Figure 4A-1d	Integrated Power per Bundle at 10.2 GWd/MT Cycle Exposure (Haling at 85% Core Flow)	4A-5

List of Figures (Continued)

Figure 4A-1e	Average Bundle Exposure at 10.2 GWd/MT Cycle Exposure (Haling at 85% Core Flow)	4A-5
Figure 4A-2a	Summary of Haling Condition — 100% Rated Core Flow	4A-6
Figure 4A-2b	Relative Axial Power at 10.5 GWd/MT Cycle Exposure (Haling at 100% Core Flow)	4A-7
Figure 4A-2c	Relative Axial Exposure at 10.5 GWd/MT Cycle Exposure (Haling at 100% Core Flow)	4A-7
Figure 4A-2d	Integrated Power Bundle at 10.5 GWd/MT Cycle Exposure (Haling at 100% Core Flow)	4A-8
Figure 4A-2e	Average Bundle Exposure at 10.5 GWd/MT Cycle Exposure (Haling at 100% Core Flow	4A-8
Figure 4A-3a	Summary of Haling Condition — 111% Rated Core Flow	4A-9
Figure 4A-3b	Relative Axial Power at 10.7 GWd/MT Cycle Exposure (Haling at 111% Core Flow)	4A-10
Figure 4A-3c	Relative Axial Exposure at 10.7 GWd/MT Cycle Exposure (Haling at 111% Core Flow)	4A-10
Figure 4A-3d	Integrated Power per Bundle at 10.7 GWd/MT Cycle Exposure (Haling at 111% Core Flow)	4A-11
Figure 4A-3e	Average Bundle Exposure at 10.7 GWd/MT Cycle Exposure (Haling at 111% Core Flow)	4A-11
Figure 4A-4a	Summary of 0.2 GWd/MT Condition	4A-12
Figure 4A-4b	Relative Axial Power at 0.2 GWd/MT Cycle Exposure	4A-13
Figure 4A-4c	Relative Axial Exposure at 0.2 GWd/MT Cycle Exposure	4A-13
Figure 4A-4d	Integrated Power per Bundle at 0.2 GWd/MT Cycle Exposure.....	4A-14
Figure 4A-4e	Average Bundle Exposure at 0.2 GWd/MT Cycle Exposure.....	4A-14
Figure 4A-5a	Summary of 1.1 GWd/MT Condition	4A-15
Figure 4A-5b	Relative Axial Power at 1.1 GWd/MT Cycle Exposure	4A-16
Figure 4A-5c	Relative Axial Exposure at 1.1 GWd/MT Cycle Exposure	4A-16
Figure 4A-5d	Integrated Power per Bundle at 1.1 GWd/MT Cycle Exposure.....	4A-17
Figure 4A-5e	Average Bundle Exposure at 1.1 GWd/MT Cycle Exposure.....	4A-17

List of Figures (Continued)

Figure 4A-6a Summary of 2.2 GWd/MT Condition (before rod sequence exchange) 4A-18

Figure 4A-6b Summary of 2.2 GWd/MT Condition (after rod sequence exchange) 4A-19

Figure 4A-6c Relative Axial Power at 2.2 GWd/MT Cycle Exposure
(before rod sequence exchange) 4A-20

Figure 4A-6d Relative Axial Power at 2.2 GWd/MT Cycle Exposure
(after rod sequence exchange) 4A-20

Figure 4A-6e Relative Axial Exposure at 2.2 GWd/MT Cycle Exposure 4A-21

Figure 4A-6f Integrated Power per Bundle at 2.2 GWd/MT Cycle Exposure
(before rod sequence exchange) 4A-22

Figure 4A-6g Integrated Power per Bundle at 2.2 GWd/MT Cycle Exposure
(after rod sequence exchange) 4A-22

Figure 4A-6h Average Bundle Exposure at 2.2 GWd/MT Cycle Exposure 4A-23

Figure 4A-7a Summary of 3.3 GWd/MT Condition 4A-24

Figure 4A-7b Relative Axial Power at 3.3 GWd/MT Cycle Exposure 4A-25

Figure 4A-7c Relative Axial Exposure at 3.3 GWd/MT Cycle Exposure 4A-25

Figure 4A-7d Integrated Power per Bundle at 3.3 GWd/MT Cycle Exposure 4A-26

Figure 4A-7e Average Bundle Exposure at 3.3 GWd/MT Cycle Exposure 4A-26

Figure 4A-8a Summary of 4.4 GWd/MT Condition (before rod sequence exchange) 4A-27

Figure 4A-8b Summary of 4.4 GWd/MT Condition (after rod sequence exchange) 4A-28

Figure 4A-8c Relative Axial Power at 4.4 GWd/MT Cycle Exposure
(before rod sequence exchange) 4A-29

Figure 4A-8d Relative Axial Power at 4.4 GWd/MT Cycle Exposure
(after rod sequence exchange) 4A-29

Figure 4A-8e Relative Axial Exposure at 4.4 GWd/MT Cycle Exposure 4A-30

Figure 4A-8f Integrated Power Bundle at 4.4 GWd/MT Cycle Exposure
(before rod sequence exchange) 4A-31

Figure 4A-8g Integrated Power per Bundle at 4.4 GWd/MT Cycle Exposure
(after rod sequence exchange) 4A-31

Figure 4A-8h Average Bundle Exposure at 4.4 GWd/MT Cycle Exposure 4A-32

Figure 4A-9a Summary of 5.5 GWd/MT Condition 4A-33

List of Figures (Continued)

Figure 4A-9b	Relative Axial Power at 5.5 GWd/MT Cycle Exposure	4A-34
Figure 4A-9c	Relative Axial Exposure at 5.5 GWd/MT Cycle Exposure	4A-34
Figure 4A-9d	Integrated Power per Bundle at 5.5 GWd/MT Cycle Exposure.....	4A-35
Figure 4A-9e	Average Bundle Exposure at 5.5 GWd/MT Cycle Exposure.....	4A-35
Figure 4A-10a	Summary of 6.6 GWd/MT Condition (before rod sequence exchange)	4A-36
Figure 4A-10b	Summary of 6.6 GWd/MT Condition (after rod sequence exchange)	4A-37
Figure 4A-10c	Relative Axial Power at 6.6 GWd/MT Cycle Exposure (before rod sequence exchange).....	4A-38
Figure 4A-10d	Relative Axial Power at 6.6 GWd/MT Cycle Exposure (after rod sequence exchange).....	4A-38
Figure 4A-10e	Relative Axial Exposure at 6.6 GWd/MT Cycle Exposure	4A-39
Figure 4A-10f	Integrated Power per Bundle at 6.6 GWd/MT Cycle Exposure (before rod sequence exchange).....	4A-40
Figure 4A-10g	Integrated Power per Bundle at 6.6 GWd/MT Cycle Exposure (after rod sequence exchange).....	4A-40
Figure 4A-10h	Average Bundle Exposure at 6.6 GWd/MT Cycle Exposure.....	4A-41
Figure 4A-11a	Summary of 7.7 GWd/MT Condition	4A-42
Figure 4A-11b	Relative Axial Power at 7.7 GWd/MT Cycle Exposure	4A-43
Figure 4A-11c	Relative Axial Exposure at 7.7 GWd/MT Cycle Exposure	4A-43
Figure 4A-11d	Integrated Power per Bundle at 7.7 GWd/MT Cycle Exposure.....	4A-44
Figure 4A-11e	Average Bundle Exposure at 7.7 GWd/MT Cycle Exposure.....	4A-44
Figure 4A-12a	Summary of 8.8 GWd/MT Condition (before rod sequence exchange)	4A-45
Figure 4A-12b	Summary of 8.8 GWd/MT Condition (after rod sequence exchange)	4A-46
Figure 4A-12c	Relative Axial Power at 8.8 GWd/MT Cycle Exposure (before rod sequence exchange).....	4A-47
Figure 4A-12d	Relative Axial Power at 8.8 GWd/MT Cycle Exposure (after rod sequence exchange).....	4A-47
Figure 4A-12e	Relative Axial Exposure at 8.8 GWd/MT Cycle Exposure	4A-48

List of Figures (Continued)

Figure 4A-12f Integrated Power per Bundle at 8.8 GWd/MT Cycle Exposure
(before rod sequence exchange).....4A-49

Figure 4A-12g Integrated Power per Bundle at 8.8 GWd/MT Cycle Exposure
(after rod sequence exchange).....4A-49

Figure 4A-12h Average Bundle Exposure at 8.8 GWd/MT Cycle Exposure.....4A-50

Figure 4A-13a Summary of 9.9 GWd/MT Condition4A-51

Figure 4A-13b Relative Axial Power at 9.9 GWd/MT Cycle Exposure4A-52

Figure 4A-13c Relative Axial Exposure at 9.9 GWd/MT Exposure.....4A-52

Figure 4A-13d Integrated Power per Bundle at 9.9 GWd/MT Cycle Exposure.....4A-53

Figure 4A-13e Average Bundle Exposure at 9.9 GWd/MT Cycle Exposure.....4A-53

Figure 4A-14 Minimum Critical Power Ratio (MCPR) as a Function of Cycle Exposure
(Four Rod Sequence Exchanges)4A-54